

Project **Setup** Zones Systems Resources Macros Interfaces Tools Configuration Help

### Setup

Data & Time  
**Integration Protocols**  
 Network  
 Khimo Cloud Link  
 System modes  
 Units

#### Home Integration Protocol

Over ethernet

TCP port:

Enable

---

**Realtime log from Masterlink Gateway Protocol**

```

15:38:34: Channel not ready, retrying in 10 seconds
15:38:44: Failed to open port (. connection failure).
15:38:44: Channel not ready, retrying in 10 seconds
15:38:54: Failed to open port (. connection failure).
15:38:54: Channel not ready, retrying in 10 seconds
15:38:54: Channel not ready, retrying in 10 seconds
15:39:04: Failed to open port (. connection failure).
15:39:04: Channel not ready, retrying in 10 seconds

```

System connection status: Beolink Khimo Cloud Link TP-Link Smart Plug #1 TP-Link Smart Plug #2 Masterlink Gateway Protocol TP-Link Power Strip FWA400

BeoLiving Intelligence v2.2.1.471

**MLGW | Foghamshire** [Help]

Info System Programming Tools Change admin password

Configuration Monitor **System logs** Error history Software Update Service report

#### System logs

```

2021-04-01 09:22:09 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP
2021-04-01 09:22:09 warn server: Administrator password not changed
2021-04-01 09:22:11 notice server: Initializing configuration
2021-04-01 09:29:31 notice server: Initializing configuration
2021-04-01 11:30:14 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP
2021-04-12 11:33:30 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP
2021-04-12 11:34:49 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP
2021-04-12 11:35:02 notice server: BeoLink driver: RS232 port serving MLGW Protocol.
2021-04-12 11:35:02 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP
2021-04-12 11:36:49 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP
2021-04-12 11:37:28 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP
2021-04-12 11:38:39 notice server: BeoLink driver: RS232 port serving MLGW Protocol.
2021-04-12 11:38:39 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP
2021-04-12 11:41:55 notice server: BeoLink driver: RS232 port serving MLGW Protocol.
2021-04-12 11:41:55 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP
2021-04-12 11:43:36 notice server: BeoLinkDriver: BiCore: Accepting MLGW Protocol connections on TCP

```

[Update information](#)

[About Bang & Olufsen Masterlink Gateway](#)
[Switch text size](#)